

The Trail Inventory of DeSoto NWR Missouri Valley, IA



Prepared By:
Federal Highway Administration
Central Federal Lands Highway Division
January, 2012



TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
I. <u>TRAIL AND TRAIL FEATURE SUMMARIES</u>	1 - 1
II. <u>TRAIL LOCATION MAPS</u>	2 - 1
III. <u>TRAIL IDENTIFICATION LIST</u>	3 - 1
IV. <u>TRAIL CONDITION RATING SHEETS</u>	4 - 1
V. <u>TRAIL DEFICIENCY RATING SHEETS</u>	5 - 1
VI. <u>PHOTOGRAPHIC SHEETS</u>	6 - 1
VII. <u>GLOSSARY</u>	i

DeSoto NWR

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface Type	Excellent		Total
	Miles	%	Miles
Native	0.75	100%	0.75
Gravel	1.79	100%	1.79
Asphalt	0.07	100%	0.07
Concrete	0.16	100%	0.16
Boardwalk	0.08	100%	0.08
Mowed	0.79	100%	0.79
Total	3.64	100%	3.64

Trail Miles and Percentages by Trail Classification and Condition

Trail Classification	Excellent		Total
	Miles	%	Miles
TC3	2.62	100%	2.62
TC4	0.79	100%	0.79
TC5	0.23	100%	0.23
Total	3.64	100%	3.64

*Admin Roads are included in the inventory but are not rated for condition.

Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T300	Sign	2	No	0.00	DESO_C2_0784
T300	Sign	1	No	0.00	DESO_C2_0786
T300	Trailhead	1	No	0.00	DESO_C2_0785
T300	Bench	1	No	0.07	
T300	Bench	1	No	0.17	
T300	Bench	1	No	0.31	
T300	Culvert -lf	20	No	0.46	
T300	Bench	1	No	0.59	
T300	Boardwalk -lf	100	No	0.71	DESO_C2_0787
T301	Sign	1	No	0.00	DESO_C2_0788
T301	Trailhead	1	No	0.00	DESO_C2_0789
T301	Sign	1	No	0.00	DESO_C2_0788
T301	Bench	1	No	0.58	
T301	Intersection	1	No	0.73	
T302	Trailhead	1	No	0.00	DESO_C2_0791
T302	Sign	2	No	0.00	DESO_C2_0792
T302	Gate	1	No	0.00	
T302	Sign	1	No	0.00	DESO_C2_0790
T302	Sign	1	No	0.03	DESO_C2_0794
T302	Sign	10	Yes	0.03	DESO_C2_0793
T302	Bench	1	No	0.03	
T302	Sign	1	No	0.05	DESO_C2_0795
T302	Bench	2	No	0.26	
T302	Other	1	No	0.66	
T302	Bench	1	No	0.72	
T400	Bridge -sf	252	No	0.00	DESO_C2_0780
T400	Trailhead	1	No	0.00	DESO_C2_0780
T400	Intersection	1	No	0.00	

T400	Sign	1	No	0.01	DESO_C2_07 81
T400	Sign	1	No	0.07	DESO_C2_07 83
T400	Bench	1	No	0.24	
T400	Bench	1	No	0.44	
T400	Bench	1	No	0.66	
T400	Bench	1	No	0.79	
T500	Bench	1	No	0.00	
T500	Trailhead	1	No	0.00	DESO_C2_07 76
T500	Sign	2	No	0.00	DESO_C2_07 77
T500	Lookout/Ob Deck	1	No	0.08	
T500	Sign	1	No	0.08	DESO_C2_07 79
T500	Lookout/Ob Deck	1	No	0.11	
T500	Max Grade- %	15	No	0.12	
T501	Sign	1	No	0.00	DESO_C2_07 97
T501	Trailhead	1	No	0.00	DESO_C2_07 96
T501	Lookout/Ob Deck	1	No	0.06	
T501	Begin Section	1	No	0.07	DESO_C2_08 00
T501	Sign	2	No	0.07	DESO_C2_07 99
T501	Bench	2	No	0.07	
T501	Lookout/Ob Deck	1	No	0.30	
T501	Begin Section	1	No	0.31	DESO_C2_08 01
T501	Begin Section	1	No	0.39	DESO_C2_08 03

sf - square feet

lf - linear feet

cf - cubic feet


DeSoto NWR Trail Location Map



Station Boundary



HQ/VC





Trails ID

Station Name: DeSoto NWR

Org Code: 33510

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Wood Duck Trail	Mowed	10012849	0.79	From Woodduck Nature Trail Parking Area (Rte 919) to end of trail
T301	Grassland Nature Trail	Gravel	10012866	0.73	From Cottonwood Nature Trail Parking Area (Rte 906) to Cottonwood Nature Trail
T302	Cottonwood Nature Trail	Native	10012829	0.75	From Cottonwood Nature Trail Parking Area (Rte 906) to Grassland Nature Trail
T400	Missouri Meander Foot Trail	Gravel	N/A	0.79	From Missouri Meander Trail w/viewing area (T500) to end of trail loop
T500	Missouri Meander Trail w/viewing area	Concrete	10012846	0.16	From Visitor Center Parking (Rte 900) to end of trail loop
T501	Bertrand Excavation Site Trail	Asphalt	10012870	0.07	From Excavation Site Parking Area #1 (Rte 907) to end of trail loop
T501	Bertrand Excavation Site Trail	Boardwalk	10012870	0.08	From Excavation Site Parking Area #1 (Rte 907) to end of trail loop
T501	Bertrand Excavation Site Trail	Gravel	10012870	0.27	From Excavation Site Parking Area #1 (Rte 907) to end of trail loop

TRAIL CONDITION



Trail Name: Wood Duck Trail
Trail Number: T300

Refuge Name: DeSoto NWR
Region: 3


Total Length: 0.79 Miles

Section Number	001
Section Length (miles)	0.79
SAMMS Number	10012849
Rating Date	09/12/2006
Trail Section Information	
Trail Class	TC3
Surface Type	Mowed
Surface Firmness	Firm
Width (inches)	96
Average Grade (%)	4.1
Average X-slope (%)	2.40
Trail Condition Information	
Deferred Maintenance	
CRV	\$34,027
FCI	0.00
Condition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$34,027	0.00	Excellent

TRAIL CONDITION



Trail Name: Grassland Nature Trail
Trail Number: T301

Refuge Name: DeSoto NWR
Region: 3


Total Length: 0.73 Miles

Section Number	001
Section Length (miles)	0.73
SAMMS Number	10012866
Rating Date	09/12/2006
Trail Section Information	
Trail Class	TC3
Surface Type	Gravel
Surface Firmness	Hard
Width (inches)	72
Average Grade (%)	3.4
Average X-slope (%)	1.50
Trail Condition Information	
Deferred Maintenance	
CRV	\$102,902
FCI	0.00
Condition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$102,902	0.00	Excellent

TRAIL CONDITION



Trail Name: Cottonwood Nature Trail
Trail Number: T302

Refuge Name: DeSoto NWR
Region: 3



Total Length: 0.75 Miles

Section Number	001
Section Length (miles)	0.75
SAMMS Number	10012829
Rating Date	09/12/2006
Trail Section Information	
Trail Class	TC3
Surface Type	Native
Surface Firmness	Hard
Width (inches)	72
Average Grade (%)	3.0
Average X-slope (%)	1.40
Trail Condition Information	
Deferred Maintenance	
CRV	\$96,912
FCI	0.00
Condition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$96,912	0.00	Excellent

TRAIL CONDITION



Trail Name: Missouri Meander Foot Trail
Trail Number: T400

Refuge Name: DeSoto NWR
Region: 3


Total Length: 0.79 Miles

Section Number	001
Section Length (miles)	0.79
SAMMS Number	N/A
Rating Date	09/11/2006
Trail Section Information	
Trail Class	TC4
Surface Type	Gravel
Surface Firmness	Hard
Width (inches)	60
Average Grade (%)	2.5
Average X-slope (%)	2.20
Trail Condition Information	
Deferred Maintenance	
CRV	\$92,801
FCI	0.00
Condition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$92,801	0.00	Excellent

TRAIL CONDITION



Trail Name: Missouri Meander Trail w/viewing Refuge **Refuge Name:** DeSoto NWR

Trail Number: T500

Region: 3

Total Length: 0.16 Miles

Section Number	001
Section Length (miles)	0.16
SAMMS Number	10012846
Rating Date	09/11/2006
Trail Section Information	
Trail Class	TC5
Surface Type	Concrete
Surface Firmness	Paved
Width (inches)	78
Average Grade (%)	4.1
Average X-slope (%)	1.30
Trail Condition Information	
Deferred Maintenance	\$329
CRV	\$35,066
FCI	0.01
Condition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$329	\$35,066	0.01	Excellent

TRAIL CONDITION



Trail Name: Bertrand Excavation Site Trail

Refuge Name: DeSoto NWR

Trail Number: T501

Region: 3


Total Length: 0.42 Miles

Section Number	001	002	003	004
Section Length (miles)	0.07	0.24	0.08	0.03
SAMMS Number	10012870	10012870	10012870	10012870
Rating Date	09/12/2006	09/12/2006	09/12/2006	09/12/2006
Trail Section Information				
Trail Class	TC5	TC3	TC3	TC3
Surface Type	Asphalt	Gravel	Boardwalk	Gravel
Surface Firmness	Paved	Hard	Paved	Hard
Width (inches)	72	60	72	60
Average Grade (%)	2.8	2.8	2.8	2.8
Average X-slope (%)	3.30	3.30	3.30	3.30
Trail Condition Information				
Deferred Maintenance	\$184		\$208	
CRV	\$12,656	\$28,193	\$55,881	\$3,524
FCI	0.01	0.00	0.00	0.00
Condition	Excellent	Excellent	Excellent	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$392	\$100,254	0.00	Excellent

TRAIL DEFICIENCY



Trail Name: Missouri Meander Trail w/viewing : Refuge Name: DeSoto NWR



Trail Number: T500

Region: 3

Total Length: **0.16 Miles**

Mile Post	0.06
Section Number	001
Photo Number	DESO_C2_0778
Deficiency	Other
Action	Repair
Item	Tread -sf
Quantity	90
Deferred Maintenance	\$329

TRAIL DEFICIENCY



Trail Name: Bertrand Excavation Site Trail

Refuge Name: DeSoto NWR

Trail Number: T501

Region: 3

Total Length: 0.42 Miles

Mile Post	0.00	0.39
Section Number	001	003
Photo Number	DESO_C2_0798	DESO_C2_0802
Deficiency	Erosion	Trail Structure
Action	Repair	Repair
Item	Tread -sf	Boardwalk -lf
Quantity	50	10
Deferred Maintenance	\$184	\$208

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T300
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0785 - MP 0.00 - Trailhead

TRAIL NUMBER: T300
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0784 - MP 0.00 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T300

STATION: DeSoto NWR

DATE: 09/12/2006



Photo # DESO_C2_0786 - MP 0.00 - Sign

TRAIL NUMBER: T300

STATION: DeSoto NWR

DATE: 09/12/2006



Photo # DESO_C2_0787 - MP 0.71 - Boardwalk -lf

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T301
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0789 - MP 0.00 - Trailhead

TRAIL NUMBER: T301
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0788 - MP 0.00 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T301
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0788 - MP 0.00 - Sign

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0791 - MP 0.00 - Trailhead

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0790 - MP 0.00 - Sign

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006




Photo # DESO_C2_0792 - MP 0.00 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0793 - MP 0.03 - Sign

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0794 - MP 0.03 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T302
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0795 - MP 0.05 - Sign

TRAIL NUMBER: T400
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0780 - MP 0.00 - Trailhead

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T400
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0780 - MP 0.00 - Bridge -sf

TRAIL NUMBER: T400
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0781 - MP 0.01 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T400
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0783 - MP 0.07 - Sign

TRAIL NUMBER: T500
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0776 - MP 0.00 - Trailhead

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T500
STATION: DeSoto NWR
DATE: 09/11/2006




Photo # DESO_C2_0777 - MP 0.00 - Sign

TRAIL NUMBER: T500
STATION: DeSoto NWR
DATE: 09/11/2006



Photo # DESO_C2_0779 - MP 0.08 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0796 - MP 0.00 - Trailhead

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0797 - MP 0.00 - Sign

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0799 - MP 0.07 - Sign

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0800 - MP 0.07 - Begin Section

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0801 - MP 0.31 - Begin Section

TRAIL NUMBER: T501
STATION: DeSoto NWR
DATE: 09/12/2006



Photo # DESO_C2_0803 - MP 0.39 - Begin Section

Glossary of Terms and Abbreviations

Acc Info	Accessibility information available at trailhead.
Action	Action required to correct deficiency.
Admin Road	Administration Road. Admin Roads signed and advertised as trails are included in the trail inventory but a condition assessment is NOT done.
Alt SAMMS	SAMMS number of Alternate Facility Type.
Alt Type	Alternate Facility Type. Trail lies on a feature such as a levee, dam, administrative road or bridge, which has a separate SAMMS number.
AvgGrade	The average grade of the trail (%). The average of five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.
AvgSlope	The average cross-slope of the trail (%). The average of five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.
Check Dam	A small dam constructed across a drainage ditch, swale, or channel to lower the speed of concentrated flows.
Condition	Subjective rating of trail based on Facility Condition Index (FCI): FCI \leq .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI $>$.20 = Failed
Crib Wall	Retaining wall.
Current Replacement Value (CRV)	The value of an asset determined by the estimated cost of replacing it.
Def type	Deficiency Type: Trail Structure, Drainage, Erosion, Obstacle, Trail Location, Other.
Deferred Maintenance (DM)	Maintenance that was not performed when scheduled.

Elem ID	Unique identifier for each trail section: Org Code-Trail Number-Section Number.
Facility Condition Index (FCI)	DM/CRV
Grouped Features	Grouped features include non-unique signs (mileposts, interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the “quantity” field of the data dictionary.
Info Type	Type of accessibility information available at trailhead: brochure, sign or other.
Item	Item on which the “Action” (see above) will be performed.
Manage_Use	Managed use of the trail: HIKE, BIKE, NSPC (non-specified), PACK, POR (portage), SNOWSHOE, XSKI (cross-country ski), OTHER.
MP	Distance of a trail feature or deficiency from the Trailhead.
Puncheon	Log footbridge used in area of poor drainage.
Raised Trail Structure	Boardwalk, Turnpike, Puncheon.
T Class	Trail Class: I-V (see Appendix ? for trail class descriptions).
Tr Desig	Trail Designation: Standard (Std), National Historic Trail (NHT), National Recreation Trail (NRT), National Scenic Trail (NST).
Turnpike	Trail tread elevated with dirt, rock or other aggregate from parallel side ditches and held in place by logs.